Machinery.

Index to Vol. 6.
September, 1899, to August, 1900.

1900.
THE INDUSTRIAL PRESS.
9 to 15 Murray St.,
New York.

24797

Index to Vol. VI.

Air Compressor, A Novel 17
Among the Shops:
Watson-Stillman Co., Some Notes on the Manufacture of Hydraulic Machinery, Gathered in the Shops of the, ... 47
Arthur Co., New York, Some Interesting Notes Taken in the Shops of the, ... 129
Dies and Drop Forgings, The Manufacture of 207
Bullard Machine Tool Co., Enlarged Plant of,—Striking Examples of Jig Work 257
Hamilton Machine Tool Co.'s Works, Hamilton, Ohio—A Few Snap Shots, Photographic and Otherwise 335
Schenectady Locomotive Works, Some of the Interesting Features of 367
Accurate Machine, An 363
Armament and Armor Plates, About 244
As Seen by a Designer. W. H. Sargent 193
A. S. M. E., Abstracts of Papers Presented at the Cincinnati Meeting of, ...297-303
A. S. M. E. Abroad 237
A. S. M. E. Meetings, The Coming, ... 104
A. S. M. E., New President of.. 131
Automatic Dividing Engine, An 244

Ball Bearing Requirements..... 150
Ball Bearings. D. T. Randall .. 332
Bethlehem Steel Co., Shops of the 65
Billings & Spencer Shops, At the 204
Boating on the Ohio 333
Boiler Thrust Bearing, A 8
Boring Engine Cranks, Fixture for 356
Boring Machine, Special 229
Bushing a Locomotive Cylinder 172

Case Hardening 157
Centering Device 158
Centering Machine 187
Chemistry in Machine Shop Practice. Warren E. Willis .. 11
Cincinnati Meeting, At the 317
Compressed Air in the Shop.. 97
Controlling Direct-Connected Motors, Method of, Wm. Baxter, Jr 201
Convenient Attachment, A..... 383
Conversion of Formulas, J. J. C. (1) 267
(2) 304
Cotton Spinning Machinery, Early. W. Midgley 268
Cutter, New Key-way 382

Disc Grinder, A Universal 72
Drafting Room, A Model, X. Y 144
Drafting Room, A Modern 161
Draftsmen's Angle Indicator .. 91
Drill, Large Multiple Spindle.. 204
Drill, Multiple Spindle 200
Drill Press, Four Spindle 90

Editorial:
Book Reviews 142
Chance for Greater Usefulness A 334
Circulation Figures, Some .. 272
College Degrees, ... 143
Compressed Air 110
Cost of the Coal Pile 78
Diamond Tools in the Machine Shop 270
Giving vs. Withholding Information 174
Influence of a Foreman 78
Iron vs. Steel 46
Laboratory Work 238
Lathe Spindles 302
Object Lesson, An 206
Paris Exposition, The 302
Rights of Advertisers, The .. 142
Seeking Promotion 110
Shipping Law, a Needed 334
Technical Papers 46
Useless and Useful Attachments on Machine Tools .. 366

Electrical Protection of Safes. .. 54
Engine Efficiency 62
Engineering Difficulties of the South African War 309
Epicyclic Gearing (2) 262
(3) 379
Equations 143
Evolution of Archimedes, The, (1) Junius 233
(2) 265
(3) 305
Expanding Mandrel, New 224
Exposition, Mechanical Features of the, Warren E. Weinsheimer 292

Familiar Subjects in Mechanics, (4) Samuel Webber 9
(5) 43
(6) 81
Flywheel Designing, C. H. Benjamin 58
Fillets and Round Corners on Castings 91
Floating Machine Shop, A..... 168
Forming Device, A Simple 123
Franklin Institute Anniversary.. 91

Gas Engine Design. E. W. Roberts.
(1) Explanation of General Principles 75
(2) Laying Out an Ideal Diagram, Directions for 137
(3) Calculating Dimensions, after Main Proportions Have Been Determined, Directions for 169
(4) Cylinder Heads and Valve Arrangement 211
(5) Pistons, Connecting Rods and Cranks 241
(6) Balance Weights and Flywheels, The Design of... ... 281
(7) The Valve Gear 307
(8) Igniters, Their Classification and Design 329
Gear Cutter, Brainard 383
Gear Shaper Improvements 167

Hand Drill, Universal 158
Hardening Solution 70
Historical Notes 237
Hour in One of the Older Shops, An 166

Inserted Tool Holder, Simple .. 224
Items of Mechanical Interest.. 8
(2) 122
(3) 230
(4) 264
(5) 371

Jones Engineering Co., Ltd., The, (1) W. H. S. 7
(2) A Blow-off 42
(3) Lesson in Projection, A.. 73
(4) Line of Shafting, A.. 111
(5) Comedy of Errors, A 149
(6) Mr. Jones Tries to babbitt an Engine Bearing.. .. 171
Junior M. E. Meeting 125

Keys and Split Hubs 327

Life and Methods in a German Shop. Robert Grimshaw 62
Liner, New German 384
Liquid Air 327
Locomotive Practice in England 115
Locomotives Used as "Sluggers" 45
Locomotives with Armor Steel Frames 354
Lost Found, The 168

Machinery at the Paris Exposition. Andrew D. Fuller..... 325
Machine Tools, Their Construction and Manipulation. W. H. VanDervoort.
(2) Lathe Feed and Screw-cutting Mechanisms 15
(3) Testing and Adjusting Engine Lathes 41
(4) Driving Lathe Work 79
(5) Lathe Tools 107
(6) Turning Long Work, and Offset Turning 147
(7) Boring in the Lathe 185
(8) Ball and Irregular Turning 319
(9) Lathe Attachments 339
(10) Planing Machines 361
Machine Work at Schenectady.. 123
Manchester Works and Its Products. James Vose 225
Measuring Machine Attachment. Robert Grimshaw 109
Mechanism, A Novel 45
Meeting of Architects and Marine Engineers 104
Micrometer Attachments 90
Milling Machine, Hand and Power Feed 296
Motive Power for Automobiles, Comparison of 114
Multiple Threads, Cutting..... 374

New School Year, The 14
New Tools of the Month 224
(2) 255
(3) 286
(4) 348
New York Harbor Fire, The .. 354
Notes from a Well-known Shop. 196
Notes from Notown, (1) I. Podunk 111
(2) 205
Notes of the Month 124
Numbering Hammer 245

Oceanic, The 38
Of Interest to Draftsmen 200
Oldest Iron Steamship in the World, The 49

Paris Exposition of 1900, The. Andrew D. Fuller 289
Patent Office Resolutions 193
Pattern Keeping, A System of. G. H. Hall 61
Pipe Bending. R. P. Perry..... 93
Pipe Cutting Machine 124
Piston-rod Roller, A..... 122
Practical Problem, A 157
Principles of Ornament, A Few. W. H. Sargent 353
Pumps, Specifications for 77
Punches for Iron and Steel. I. P. Richards 309
Pyrometers. William Wallace Christie 105

Recent Developments in the Halifax (Eng.) District. Jas. Vose 146
Report of the Bureau of Steam Engineering 124
Rig for Engine Frames, Boring. Chas. Fosdick 173
Rules for the Shops, Some Useful. I. McKim Chase 355

Saw for Machine Shops, Circular. 178
School of Electricity, A 74
Screw Pitches in Foreign Countries 164
Secor Works, Notes from the .. 226
Sensitive Drill, Four-Spindle .. 222
Sensitive Drill, New 185
Shaper Feed Motions 229
Shaper, Large, Traveling-head.. 326
Shop Motor, A Three-Cylindered 12
Shrink and Press Fits. Henry Hess 140
Simplex Centre Grinder 136
Smillie's Thread Tool 8
Soap in Hardening Water, Effects of 10
Split Collar for Shafts, English. 122
Standard Keys. Henry Hess .. 39
Steam Turbines on Large Vessels 83
Steel Forgings, Making Heavy .. 33
"Straight Edge" Was Crooked, The 56

Testing the Strength of Materials, (1) Edw. F. Miller 175
(2) 198
(3) 235
(4) 321
Todrank Tiosa and the Boss, or the Man of Few Words 365
Toggle Joints 64
Tool Holder, A Combination .. 196
Tool Holder, New Boring 158
Tool Post, A Revolving. W. A. Bright 13
Tool Rack, A Revolving 8
Transmission of Power, Notes on the 364
Traveling Stairway 269
Tumbler Gearing. P. J. Connor 109
Turret Lathe, A Universal 84
Twentieth Annual Meeting of the American Society Mechanical Engineers 132

Union Iron Works, The. J. Richards 26

Vincennes Exhibits, The. Warren E. Weinsheimer 359

Water Was Too Strong, The .. 115
Weather Was Too Damp 44
Welding Steel 219
Who Invented Steam Navigation? 63
Wireless Telegraphy. Wm. Baxter, Jr. 70
Wireless Telegraphy (note on). 124
Worth Heeding 150
Worth Noting 74
Wrench, Adjustable 122
Yankee Drill Grinder, An Improvement in the 222

Letters upon Practical Subjects.

Another Column 117
Automatic Worm-wheel Hobbing Machine 25

Beaman & Smith, New Shops of 28
Believes in Close Figuring 129
Bell Shifter, A Novel 51
Blue-printing Apparatus... 250
Belt Drive, Successful 220
Boring a Roll Under Difficulties 251

Centering Crank Shafts, Device for 342
Centering Cylinders for Facing and Turning, Methods for 120
Chamfering Cup Leathers, Etc 20
Chuck for Boring Gears, A 219
Chucks for Gears 315
Condenser of Steam Under Water, A Silent 342
Cotter Pins 275
Counterboring Tool and Other Devices 155
Cranes High and Cranes Low .. 181
Crank Pin, A Removable 28
Crank-pin Holes, Boring.. 378
Cranks, Patterns for Cast Iron.. 183
Criticisms, Some 23
Cross-Feed Nut, Fastening a .. 343
Cupped Washers for Holding Work in Gangs 117
Curve by Points, To Construct a 119
Cutter Lathe Tools, Inserted.. 151
Cutter Tools, Inserted 216
Cutting Out Keyways, Scheme for 215
Cylinder, Boring a Large 312

Die, How He Hardened the 156
Does Not Like Freak Designs .. 52
Draftsmen vs. Shopmen 247
Drawing Machine, A 180
Draw-plate for Patterns, A..... 219
Drop Hammer Foundations 314

Electrical Work, Fishing for Wires in 313
Ellipses, The Circumference of. 248
Examples of Manual Training, About Those 51
(2) 118
Expanding Copper Liners, in Cylinders, Method of 179
Experience of a Tool-building Firm, An 376

Fin is Prevented in a Large Casting, How an Objectionable 152

Gages for Bicycle Work 312
Gasoline Engines 378
Grinding 25
Gears, Spiral 276
Hack-saw Guides 313
Hammer Handles 156
Hammers, Hardening 275
Heard From 54
High and Low Prices 214
Holding Two Scales for Long Measurements, Device for 278
"How and Why" 342
Hypothenuse of a Right-angled Triangle for a Given Lift in in a Machine, Method of Finding 217

Indexing for Catalogues, Marginal 375
Indexing on the Milling Machine 246
Index Plate, Geometrical Method for Originating 344
Ingenious Scheme, An 214

Jig for Shaping Locomotive Rocker Arms 118
Kink for the Grinding Machine 53
Key from the Solid, Cutting a.. 344
Knives for Cutting Rubber, Leather, Fiber, Etc 377

Lathe and Planer Tool Holders, About 217
Lathe, Compounding a Simple 376
Lathe Design, A Suggestion in 181
Lathe, Grooving Attachment for 344
Lathe Rig for Backing Off Milling Cutters, Simple 216
Lathe Shears 275
Lathe Testing Machine, A Novel 152
Lamp, Pneumatic, Self-heating.. 371
Lead Screw, A Reversible 155
Lead Screw, Cutting a 183
Leveling Work 179

Machine Design, Small Things in 182
Machine Shops, Conservatism in 275
Magnetism, One Use for 119
Milling Machine, A Plain 32
Multiple Threads, To Cut 216

Notes from Philadelphia, Some; Using Hartness Tool Holders in Engine Lathes 250
Numbering Patterns and Drawings 153

Odds and Ends for the Shop.... 117
Oil Holes in Machinery 278
Oil Tank, Moving an 314
Order Numbers and Time Cards 53

Paris, Advice Concerning 277
Patterns for Cast Iron Cranks.. 183
Patterns, Rap and Draw Plates for 315
Phenomenon, A Curious 153
Planer Feed Mechanism 343
Pipe Machine, Target and Scale for 346
Piston Valves, A Texas Method of Fitting 250
Pitch of Milling Cutter Teeth .. 180
Planer, A Large 310
Power Producer, About the .. 24
Practical Problems 26
Professional Consultation vs. Mechanical Advice 346
Pulley Weights, Diagram of. Wm. Sangster 29

Radiators Filling with Water, To Prevent 247
Reading Advertisements 214
Reamers, Irregularly Spaced .. 52
Remarks by a Machinist 116
Rig for Grinding Carbon Brushes 248
Rust on Soldered Articles, To Prevent 184

Salt and Pepper Shaker Caps... 249
Section Liner 154
Section Spacer, A 156
Shaper Design, Another Novel 50
Shaper Ram, About the Form of a 22
Shaper Slides 24
Shaper Slides Again, About.... 50
Shaper Slides and Oiling Conveniences, Regarding 344
Shaper Slides, The Adjustment of 276
Shop System, Another 21
Speed Device, Variable 313
Steam Boilers, A Gravity Supply for 247
Steam Heating, Radiating Surface for 310
Step Bearing for Heavy Duty, Details of a 23
Squaring Partitions 215
Supporting Lead Screw on Old Lathe, Method of 247

Takes Exception to Proposed Shaper Slide 116
Testing and Adjusting Engine Lathes in Germany 119
Testing Engine Lathes 151
Thread Cutting, Practical Problems in 153
Thread Cutting, Solutions and Suggestions to the Problem in 218
Threading Job, A Difficult 215
Threading Taps, with Shrinkage Allowance 315
Tool Chest, A 278
Tool Chests 375
Tool for Setting an Oil Tube, A 179
Tool Holder for Planer 151
Tool Holder for Planer, Extension 276
Tool Holder, Novel Turret 310
Tool Holders, About Inserted .. 185
Tools, Curious Method of Keeping 311
Trammel, Improvised 215
Triangles, Utilizing Broken 277
Triangle with Scale, Draftsman's 343
Trolley Wheels, Milling 116
Turning Link Blocks 116

Utilize the Cooling Water of Gas Engines, To 30

Variable Speed Motor 28

Wheel Teeth Design, Points in 184
Where is He? 22
Worm-wheel Hobbing Machine 25
Wrinkle in Cooling Machine .. 25

Shop Kinks.

Babbitting Boxes 83
Blacksmiths' Calipers 83
Boring Tool 82
Buffalo Kinks, Some 18

Center Indicator 232
Centering Device 274
Centers for Pipes, Columns, Etc., Expanding 232
Change Gears, Convenience for 82
Chisel for Chipping Steel 57
Clamp for Holding Work on Face Plate 18
Coil Springs in a Vise, To Make 273
Combination Tool, A Good .. 373

Die, A Ring-cutting 18
Die for Cutting Slots 82
Die for the Blacksmith Shop, Handy 374
Drill Holder 272

Expanding Centers for Pipes, Columns, Etc 232
Extension Cutter Bars, Two 273

Facing Rig, A Neat 232
Facing Tool 232
From Down in Texas 122

Gage, Tool-setting 374

Handy Tool, A 373

Jack for Straightening Shafting 18
Jig Bushing 220

Lapping Holes with Emery Cloth 374
Lathe and Planer Kinks, Some 183
Lathe Making in Vermont 220
Lead Screw, Cutting a 183
Malleable Cast Iron 19
Milling Rig for the Lathe 273

Nickel Steel Tubes 57

Pennsylvania Shop Kinks, Some 121
Planer Poppets 373
Press Work in a Lathe, To do 231

Reamer, Adjustable 273
Rig for Cutting Long Racks on the Milling Machine 56

Scratch Gage, with Micrometer Adjustment, A 53
Section Liner 82
Self-oiling Pulley 53
Slots, To Save Labor in Making 18
Surface Gage, with Two Pointers 231

Tail-stock, To Set a 272
Taper Indicator for the Lathe 274
Taper Reamer 220
Taps, Hardening 121
Thread Tool, An Inside 121
Threading Small Screws, Method for 373
Tool Relieving Device 231
Turning Circular Grooves, Lathe Tools for 373
Turret Lathe Tool 274
Two from Pennsylvania 220
Two Providence Kinks 220

Vise Clamps for Finished Work 82
Vise Jaw, for Holding Tapered Work 121

How and Why.

39. Angle of a Tool for Cutting Coarse, Square Threads, To Find the 189
69. Angles, How to Measure . 348
32. Annealing Mushet Steel.... 159
4. Appropriate Books for an Engineer to Study for a License 32

26. Balancing a Vertical Engine 159
45. Ball Pene Hammer, To Harden 239
61. Batteries, Text Book on.. 286
25. Belt Holes in Floor, Methods of Laying Out for Quarter 127
37. Bessemer Steel, Hardening 189
64. Bicycles, Relative Strength of High and Low 347
11. Books on Gas and Oil Engines 94
30. Books Upon Lubricants .. 159
56. Brass, To Color, a Dull Black 285

13. Carbon, Effect of, in Hardening Steel and Iron 94
20. Catching the Thread 126
16. Cement Joint, How to Make 95
16. Cemented Belt Joint, Advantage of 95
66. Change Gears, Method of Calculating 347
67. Combined Steam and Gasoline Engines 347
42. Commutator Sparking Badly, Cause of 190
8. Compound Gearing for Lathe 64
14. Countershaft, Position of, Above a Lathe 94
39. Course of Studies Suitable for a Tool Maker 189
20. Cutting Double, Triple and Quadruple Threads on a Lathe 126
2. Cutting Keyways in the Hub Between the Arms of a Pulley, viz.: in the Hub, at the End of an Arm 32

40. Determining the Compression in a Diesel Motor, Method of 190
6. Directions for Building a Small Engine 64
29. Draw-plates for Foundry Work 159
14. Drills, Directions for Grinding 34

52. Electrical Gage for Indicating the Height of Water in a Tank 240
65. Emery, Corundum and Carborundum, Definitions of.. .. 347
38. Expansion for Hollow Cylinders, Amount of 189

56. Fasten Babbitt Letters to Metal Patterns, To 285
23. Feed Water Purifying in Marine Practice 126
19. Fit Between the Pin and Hole of Exactly the Same Diameters, The 126
58. Flywheel for Automobile, Weight of 285
22. Foot Pounds of Work Equivalent to Thermal Units in Steam 126
9. Fusible Plugs, Composition of 64

40. Gas Required to Produce One H. P. in a Gas Engine, Amount of 190
3. Gearing of a Lathe, To Calculate the 32
28. Grinding Ammonia Cocks.. 159

39. Hardening Bessemer Steel . 189
24. Index Plate, Method of Using on Milling Machines 126
70. Internal Gears. Limit of Size of 348

59. Jump Spark in a Gas Engine, Ignition by 285

68. Lathe Centers 348
57. Lead and Pitch, Definition of 285
60. Lever Formulas in Mechanics, Solution of 285
51. Location of Brushes to Obtain Alternating or Direct Currents from Dynamo 240

41. Magnetizing a Piece of Hard Steel, Method of 190
61. Magnet, To Magnetize a Horse-shoe 286
38. Metals Having Greatest Expansion 189
7. Method for Case-Hardening, A 64

47. Offset Required to Bore a Taper Hole, Amount of 239
10. Oil Required to Produce 1 H. P. in an Oil Engine, Amount of 190

21. Phosphor Bronze, Relative Strength of, as Compared with Drop Forgings 126
3. Planing the Boxes 32
49. Press Fit, Proper Allowance for 239
1. Power Required to Operate a Steam Hammer, To Calculate the 32
12. Power Required to Propel a Yacht 94
43. Problem in Epicyclic Gearing, A 239
59. Propeller for Small Launch, Dimensions of 285
5. Proportion of Dies for Rivets 26c
36. Punching Steel 189

3. Ratio in a Series of Pulleys, To Calculate the 32
50. Reading Micrometer and Vernier Calipers 240
5. Relation Between a Circle and its Largest Contained Square, The 26c
61. Rubber, To Turn and Polish Hard 286

4. Screws for Stacks 26c
35. Setting Tool when Cutting a Taper Piece, Correct Method for 189
44. Shrinkage in Taps, when Hardened, To Overcome 239
5. Shrink Fits, Allowance for.. 26c
38. Size of an Engine to Drive an Air Compressor, To Calculate the 189
34. Soldering Aluminum 189
48. Specific Gravity, Question in Regard to 239
15. Speeds for Metal Working. 95
55. Standards for Bolts, U. S. and Franklin Institute 284
33. Steam Heating System, Trouble With 160
39. Studies Suitable for a Toolmaker, Course of 189

5. Taper of Pipe Thread 26c
10. Taper Turning 94
35. Threading a Taper Piece, Correct Method for Setting the Tool When 189
7. To Anneal Cast Steel..... ... 64
44. Tool for Cutting a Square Thread, Proper Location 239
17. Tooth Clutch for Friction Geared Headstock 126
19. Transferring Measurements by Calipers 126
31. Treatment of Steel to Prevent Rusting 159

18. Volume Contained in Saddle Tank 126

7. Welding Compounds 64
27. Wireless Telegraphy, Information About 159

24797

1105770